

WORK ORDER REQUEST

0-008356

File No. 6199

Request No. 60-19

Date: 28 Aug 1959

SUBJECT: Request for Repair (Contract No. TD16)

TO:

STATOTHR

FROM:

FOIAb3b1

Request the following items be checked for possible quality control slippage. These items failed to check out for use in the field for the reason as stated by each serial number. It is further requested that a full report be furnished as to results of the inspection.

<u>ITEM</u>	<u>PART NUMBER</u>	<u>UNIT</u>	<u>QUANTITY</u>
1.	F2400-6	EA	6 ✓
	Ser Nos.		
1.	3712		
	Excessive Suit Vent Leak		
2.	3750		
	Suit Vent Leak		
3.	3137		
	Suit Pressure Too low at all altitude		
4.	1632		
	Excessive Suit vent leak on press to test		
5.	123		
	Excessive Suit vent leak on press to test		
6.	2761		
	Low mask and suit ratio at 50 and 60 M		

FOIAb3b1

AUTHORIZED BY:

RETURN TO: PROJECT DRAGON LADY
WARNER ROBINS AIR MATERIEL AREA
ROBINS AIR FORCE BASE, GEORGIA
WAREHOUSE 17, STOCKROOM B

578
8/24/59